

Bodman Park
Market Street, Middletown, NJ
Solutions and Cost Estimates

1. Level the parking spaces to achieve a slope of less than 2%, install an access aisle between the two spaces
2. Install the signs so that the bottom of the sign measures within the ANSI and ADAAG standards provided.
3. Establish an accessible route from the parking spaces to the sidewalk that is at least 36 inches wide and has a firm, stable surface as defined by the ANSI and the ADAAG.
Total Cost for parking issues : \$1400.00
4. Replace 2 tables with some that contain the required underside clearance. Position the tables so that the 30 inches by 48 inches of clear floor space is achieved. There needs to be accessible route to this area. Cost: \$150.00 each \$300.00 Total
5. Establish an accessible route that is at least 36 inches wide and has a firm stable surface according to ANSI and ADAAG. Cost: \$600.00
6. Establish an accessible route that is at least 36 inches wide and has a firm stable surface according to ANSI and ADAAG. Cost: \$1200.00.
7. Make a path to at least one of each type of field so the public has access to the sporting events. Cost: \$1200.00-\$1600.00
8. Establish an accessible route that is at least 36 inches wide and has a firm stable surface according to ANSI and ADAAG. Cost: \$1200.00.
9. Install a curb cut for the transistion from the street to the sidewalk. Cost: \$600.00

Note:

The bathrooms were not available at the time of inspection, I would, if necessary, reserve the right to inspect and give an estimate of the required renovations.